


View 9: View of the Los Angeles Country Club golf course to the east of the project site. The golf course is secluded by dense trees and vegetation that surround its perimeter; thus, it is not directly visible from the project site.

View 10: Looking east from the project site at the Los Angeles Country Club maintenance yard, which is adjacent to the project site (just west of the golf course). The ornamental vegetation that forms the eastern boundary of the project site is visible in the foreground.





View 11: Looking south from the project site at a twostory, single-family home located on the south side of Club View Drive.

Source: Christopher A. Joseph & Associates, October 2004.

