



Photo of Hollywood Blvd. exterior of subject property. Overhead signs will be removed and replaced with more subdued signs similar to signs shown on architect's sketch enclosed. Entire site has just undergone a \$100,000 seismic reinforcement job. This has resulted in shabby exteriors. Exterior will be restored with Spanish Style textured stucco coat, canvas awnings, and new paint also similar to architect's sketch.