



- Existing Index Contour
- Existing Intermediate
- Sandbags and/or Haybales
- Flow Line

NPDES Sampling Location (with letter designation)

1.Topographic survey provided by Waste

Management. Date of Photography: 4/2004 (see

2. Conditions shown may not be indicative of present conditions



Source: Golder Associates, September 30, 2004.

Figure 4.8-3 Site Stormwater Management Plan